



JHH2-□ | Mining Intrinsically Safe Distribution Box



Use

The junction box is used in coal mine where is filled with explosive gas such as methane, coal dust and so on, mainly is used as cable distribution box to connect intrinsically safe circuits among electrical equipments, only can be used in intrinsically safe circuits.

Meaning of Type



Technical Descriptions

Safe, reliable, convenient for use, small size, light weight, high intensity, good insulation property, etc.

Technical Data

Type	Quantity of gland (pcs)	External diameter of cable (Φ mm)	Specifications of gland	Dimension L × W × H (mm)	Weight (kg)
JHH4(12 contacts)	4	6-10	M20	184 × 110 × 48	0.65
JHH2-6(A)(20 contacts)	4	5-13	M24	215 × 225 × 65	1.2
	2	6-10	M20		
JHH2-6(B)(40 contacts)	4	5-13	M24	385 × 247 × 76	2.2
	2	6-10	M20		
JHH2-6(C)(60 contacts)	2	17-24	M36	355 × 345 × 76	2.3
	1	9-17	M30		
	3	5-13	M24		
JHH2-7(A)(60 contacts)	2	22-30	M42	386 × 270 × 76	2.4
	1	17-24	M36		
	2	9-17	M30		
	2	5-13	M24		
JHH2-7(B)(60 contacts)	2	17-24	M36	326 × 270 × 76	2.3
	2	9-17	M30		
	2	5-13	M24		
JHH2-7(C)(40 contacts)	1	6-10	M20	386 × 270 × 76	2.4
	1	9-17	M30		
	4	5-13	M24		
JHH2-7(D)(40 contacts)	2	6-10	M20	250 × 295 × 65	1.3
	2	9-17	M30		
	2	5-13	M24		
JHH2-7(E)(40 contacts)	2	17-24	M36	250 × 225 × 65	1.3
	3	5-13	M24		
	4	6-10	M20		
JHH2-7(F)(20 contacts)	3	5-13	M24	535 × 350 × 100	7
	4	6-10	M20		
JHH2-10(A)(80 contacts)	4	32-40	M52	770 × 415 × 160	44.5
	2	22-30	M42		
JHH2-10(B)(100 contacts)	4	6-10	M20		
	4	32-40	M52		
	2	22-30	M42		
JHH2-22(200 contacts)	4	6-10	M20		
	2	19-51	Φ85		
	2	12-40	Φ68		
	18	6-10	M20		